Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: WO/17017UC-2087/1

Work Order Type: Weatherization

Audit Name: Audit (119)

CLIENT INFORMATION

Client Name: N/A Address:

Client ID: 17017UC-2087

Alt. Client ID: WARREN

CLIENT CONTACT INFORMATION

N/A Applicant/Person of ✓

Record

AGENCY INFORMATION

Agency: Upper Cumberland Human Resource Agency Agency Phone: (931) 528-1127

Address: 580 South Jefferson Avenue, Suite B Fax: (931) 526-8305

Cookville, TN 38501 *Email Address:*

Agency Contact: Smith, Richmond Work Phone:

Cell Phone: Email Address:

Company Name & License Number:

Contractor's Signature:

COMMENT

HOME BUILT IN 1900

AUDITOR: RICHMOND SMITH

Client Name: N/A
Client ID: 17017UC-2087
Alt. Client ID: WARREN

Work Order (Bid Form)

Work Order Name: WO/17017UC-2087/1 Report Run On: 4/9/2012 DOE Weatherization Assistant

Version 8.6.0 Page 1 of 7

Measure 1 Infiltration Redctn			Componei	nts			Inspected
Comment SEAL OFF 3 OLD FIREPLACES ADD 3/4 PLYWOOD AND CAUL W/SHEETROCK, TAPE, & MUD WOOD SLABS, W/STRIP, SWE REGLAZE AND CAULK INTERI OF SINGLE STRENGTH GLASS A18, & A21).	LK. 2 X 2 D. REPLAC EEP, THRE OR OF AL	CEILIN E DR´ ESHOL L 26 V	IG REPAIR 1 & DR2 W .D, & NEW VINDOWS.	IN KITCH SOLID CO LOCKSE REPLAC	HEN ORE TS. CE 1 PC)	
			Estimate	<i>d</i>		Actual	
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Miscellaneous Su Infiltration Reduction	Each	1					
Other Detail							
		Measur	e Sub Total:] ;	Sub Total:	
Measure 2 DWH Tank Insulation Comment			Compone	nts			Inspected
			Estimate	<u> </u>		Actual	
# Material / Labor Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Hot Water Equip DHW Tank Insulation	Each	1					
2 Labor DHW Tank Insulation	Each	1					
Other Detail							
Field Notes:		Measur	e Sub Total:] ;	Sub Total:	
		Measur	e Sub Total:			Sub Total:	
		Measur	e Sub Total:			Sub Total:	

Measure 3 Ligh	nting Retrofits			Componer	its L1,L2			Inspected
Comment								
				Estimated Actual				
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Lighting	Compact Fl 13 Watt	Each Lamp	3					
2 Labor	Compact FI 13 Watt	Each Lamp	3					
3 Lighting	Compact FI 13 Watt	Each Lamp	3					
4 Labor	Compact FI 13 Watt	Each Lamp	3					
Other Detail						,		
			Measur	e Sub Total:] ;	Sub Total:	
	H Pipe Insulation			Componer	its		1	Inspected
Comment WRAP	6 FT HOT & COLD LIN	ES @ W/H	ΓR					
				Estimated			Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	DHW Pipe Insulation	Each	1					
2 Labor	DHW Pipe Insulation	Each	1					
Other Detail						1		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								

Measure 6 Flo	or Ins. R-19			Componen	its F1			Inspected	
Comment	omment								
				Estimated	1		Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
1 Insulation	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	552						
2 Labor	Floor Insulation - Fiberglass Faced Batt - R-19	SqFt	552						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Comment REPLA DUCT\ CLOSE	place Htg. System ACE 80,000 BTU NATURA WORK. ADD 1 VENT TO ET). Description / Comment en Replacement Furnace (not used) - 50 kBtu/h NG Existing, 187-261				TO EXIS		Actual Unit Cost	Inspected Total	
	kBtu/h NG Post								
2 Labor	Replacement Furnace (not used) - 50 kBtu/h NG Existing, 187-261 kBtu/h NG Post	Each	1						
Other Detail									
			Measur	e Sub Total:			Sub Total:		
Field Notes:							-		

Client Name: N/A Client ID: 17017UC-2087 Alt. Client ID: WARREN

Work Order (Bid Form)

DOE Weatherization Assistant Work Order Name: WO/17017UC-2087/1 Version 8.6.0 Report Run On: 4/9/2012

Page 4 of 7

Measure 8 Repl	replaced the second sec							nspected
	CE EXISTING 3 TON CE REPLACING.	ENTRAL A	/C UNI	T. TIE A CC	IL TO FU	JRNAC	E	
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Cooling Equipmen	Central A/C -	Each	1					
2 Labor	Central A/C -	Each	1					
Other Detail								
			Measur	e Sub Total:] .	Sub Total:	
Measure 9 CO N	Monitor is Needed			Componen				Inspected
Comment		Unito		Estimated	<u> </u>	Oty	Actual	
	Description / Comment	<i>Units</i> Each	Qty 1	•		Qty		Inspected
Comment# Material / Labor1 Health and Safety	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety	Description / Comment CO monitor	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Health and Safety2 Labor	Description / Comment CO monitor	Each	Qty 1 1	Estimated	<u> </u>		Actual	

	ctice Lead Safe Weathe alls)	erization		Componen	Inspected				
Comment USE LI	EAD SAFE PRACTICES Y	WHEN RE	EPLAC	NG 2 EXTE	RIOR DO	OORS			
			Estimated				Actual		
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total	
10 Unspecified	Misc Material	Each	1						
Other Detail									
Other Betain									
			Moseur	e Sub Total:]	Sub Total:		
			Weasur	e Sub Total.]			
Field Notes:									
Measure 11 RE	PLACE WATER HEATER CE EXISTING 40 GAL N			•	KING).			Inspected	
Measure 11 REI Comment REPLA	CE EXISTING 40 GAL N		GAS W	•	KING).	Qty	Actual Unit Cost	Inspected	
Measure 11 RE Comment REPLA # Material / Labor		IATURAL		//HTR (LEA <i>Estimat</i> ed	KING).	Qty	Actual		
Measure 11 REI Comment REPLA # Material / Labor 10 Unspecified	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA <i>Estimat</i> ed	KING).	Qty	Actual		
Measure 11 RE Comment REPLA # Material / Labor	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA <i>Estimat</i> ed	KING).	Qty	Actual		
Measure 11 REI Comment REPLA # Material / Labor 10 Unspecified	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA <i>Estimat</i> ed	KING).	Qty	Actual		
Measure 11 REI Comment REPLA # Material / Labor 10 Unspecified	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA Estimated Unit Cost	KING).		Actual		
Measure 11 REI Comment REPLA # Material / Labor 10 Unspecified Other Detail	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA <i>Estimat</i> ed	KING).		Actual Unit Cost		
Measure 11 REI Comment REPLA # Material / Labor 10 Unspecified	CE EXISTING 40 GAL N	IATURAL <i>Units</i>	GAS W	//HTR (LEA Estimated Unit Cost	KING).		Actual Unit Cost		

Measure 12 Smoke Detector is Needed X 2				ı	Inspected			
Comment INSTA	LL 2 SMOKE DETECTOR	RS						
				Estimated	1		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
10 Unspecified	See the User Defined Measure for a list of materials.	Each	1					
Other Detail] [
						<u> </u>		
			Measur	e Sub Total:			Sub Total:	
Field Notes:								
		Work Or	rder Gra	and Total:		Gran	d Total:	